



Power supply: -10V to 4 power point D1,D7;
 0 to 7 power point D2,...D5;
 +15V to 14 power point D2,...D5;
 +20V to 7 power point D1,D7

Picture 3. Control card of control unit welding rectifier VDU-505-2 electrical schematic diagram