

2009/3/21日电子IC最新库存状况

NO.	PARTNO	DESCRIPTION 描述	牌子	Date code	ONHAND 数量	盒裝數量	帶裝數量	管裝數量	散裝數量	RoHS狀況
	代码		品牌	年号		包装				环保状况
1	00123S0036	IC OPT-CPR DIP4 PC123Y52	Sharp	0412	16188			●		非RoHS
2	00817T0236	XP3-1L	Sharp	07.01	16409		●			非RoHS
3	0017	IC REG TO220 T1UA7812CKC	TEXAS	0406	12992			●		非RoHS
4	0050	IC LINEAR TO-220 AAC AZ1084T-3.3E1	BCD	0549	12959			●		RoHS
5	0105	I.C. TC4069-0105, Toshiba TC4069-0105	Philips	0149	10423			●		非RoHS
6	0128	IC, Op-Amp, DBL324V SOP, DBL324V	OP-AMP	05.10	9924			●		非RoHS
7	0043	IC SMD 2COMP FLP-8 KIA393F-E1/P	KEC	04.07	11108	●				非RoHS
8	0025	IC REMOTE-CTR RSIP-A3 RPM7138			7159			●		RoHS
9	0208	IC LED Driver BD7851FP	RoHM	0627	7019	6000			1019	RoHS
10	0017	IC REG TO-220 T1 UA7808C	TEXAS	0344	6007			●		非RoHS
12	0001	IC PWM DIP8 SG6848D	SGS	05.05	5173			●		RoHS
13	0005	IC SMD CMOS SOP14 TC74HC126AF	Toshiba	0321	5000		●			RoHS
14	TAKA	IC HIC(AH) RH-IZA495DREO	Murata	05.10	4167	●				RoHS
15	0143	IC SMD DRIVER FLP-16 KID65004AF	KEC	02.04	3541	●				RoHS
16	TAKA	IC AT 24C01-10PC RH-IZA979DREO	ATMEL	04.08	3350					非RoHS
17	0127	ADZM05531	OKI	98.09	3116			●		RoHS
18	0043	IC DRIVER DIP16 KID65004AP/P	KEC	05.10	3113			●		非RoHS
19	0100	IC CMOS 16Pin T1 CD4022BE	TEXAS	0614	3042			●		RoHS
20	0160	LCD DRIVER RH-IZA951DRE0 EOC63454	EPSON	05.10	3000				●	RoHS
21	0040	NPN SMD 0.1A 300V SOT23 PMBTA42	NXP	0103	3000	●				RoHS
22	0100	IC SMD MCU UPD78F9456	NEC	0403	2884	●				非RoHS
24	0100	REO	IR		2771			●		非RoHS
25	TAKA	IZA897D REO	Renesas	04.06	2623			●		非RoHS
26	TAKA	IZA98	Renesas	04	2510			●		非RoHS
27	0200	IC SMD EEPROM SOP8 BR24C01AF-W	RoHM	0646	2500	●				RoHS
29	0054	IC LINEAR TO-220 AZ1084T-ADJE1	AAC	0547	2481			●		RoHS
30	0023	IC SMD OP SO14 LM6144BIM			2351	1588		763		RoHS

31	0143	IC, AP34063N, (Sytech)	SYTECH	05.10	2343			●		非RoHS
32	3007	Micro computer IC M38127M8	Renecas		2255			●		非RoHS
33	0143	IC SMD DRIVER FLP-16 KID65004AF	KEC	05.05	2233	●				非RoHS
34	0243	IC SMD DRIVER FLP-16 KID65004AF	KEC	05.06	2192	●				RoHS
35	0033	IC 74HC00 SOP16 Quad nand gate 74HC00	PHILIPS	05.08	2213	2185			28	非RoHS
36	TAKA	M38127MS M38123M6	SHARP	05.02	2021			●		RoHS
37	0100	IC SMD HEX SO14 HE 40106BT	PHILIPS	0646	1993	●				RoHS
38	0059	Power IC M51998FP Renesas	Renecas	04.12	1979			●		非RoHS
39	0038	IC SMD PWM TSSOP-20 NCP	OMSEMI	0625	1978			●		RoHS
40	0043	IC SMD 2COMP FLP-8 KIA393F-EL/P	KEC	0311	1970			●		RoHS
41	0018	IC SMD DC-DC SO-8 MC34063ACD		07.08	1967	●				RoHS
42	0042	IC MIP0255SPSCF MEC	MELUK	04.10	1890			●		非RoHS
43	0201	IC SMD 4COMP SO14 LM339DT	ST	04.09	1764	●				RoHS
44	0039	TSM1051CLT	ST		1711					RoHS
45	0005	IC TC74HC238 Supplier: Toshiba	TOSHIBA	97.10	1715			●		RoHS
46	0139	IC SMD PWM SO16 SG2525AP	ST	05.07	1650	●				RoHS
47	02703U0006	IC SMD OPT-CPR 4Pin SOP PS2703-1-F3	NEC		2189	●				非RoHS
48	TAKA	CS16J-1L	SHARP	04	1638	●				RoHS
49	0038	IC SMD COMP SOIC-8 NCP4300ADG	OMSEMI	0729	1550	●				RoHS
50	0005	IC, TMP47C623F, Toshiba	TOSHIBA		1509	●				非RoHS
51	0134	FET 9.8A 800V TO-3P SSH10N80A	Fairchild	02.09	1503			●		非RoHS
52	0005	IC SMD CMOS SOP14 TC74HC126AF	TOSHIBA	0346	1494	●				非RoHS
53	0025	IC OP DIP8 BA4558	ROHM	0411	1456			●		RoHS
54	0038	IC PWM DIP8 NCP1200P60G	OMSEMI	03.10	1360			●		非RoHS
55	0008	MEC Micro MN101C54C MEC	MEC	05.10	1348	●				RoHS
56	0017	IC SMD REG SO8 TL317CDR	TI	0619	1320			●		RoHS
57	0033	IC SMD TIMER SO8 ICM7555CD	NXP	0648	1299	●				RoHS
58	0005	IC SMD TTL SOP-18 TD62083AF	TOSHIBA	0640	1251	1018			233	RoHS
59	3COB	IC SMD MCU C38869MFA	Mitsubishi	05.02	1157	●				非RoHS
60	TAKA	VHIT7VHC244FTL	SHARP	05.05	1151	●				非RoHS
61	0041	IC SMD DC/DC SO8 AIC1631ACS	AIC	05.08	1147	1085			62	非RoHS
62	0243	IC SMD DRIVER FLP-16 KID6500AF-EL	KEC	04	1128	●				非RoHS
63	0004	Regulator BA17805T	ROHM	02.11	1073				●	RoHS
64	0134	IC REG TO-220 KA7805	Fairchild		1041			●		非RoHS
65	0000	12YE	ATMEL	07.09	1032			●		RoHS

66	0060	LCD DRIVER EPSON IZA951DR	SHARP	05.10	1000				●	RoHS
68	0136	IC PC817D SMD Sharp LTV817STA-V	SHARP	0338	985	●				非RoHS
69	0000	4N25 OPTO Coupler		05.10	932			●		非RoHS
70	1047	IC SMD REG TO-252 PJ1084CP-3.3	Promas	05.05	917	●				RoHS
71	0047	IC REG TO220 PT1084CZ-ADJ	Promas		906			●		RoHS
72	0017	IC REG TO-220 UA7808C	TI	0406	890			●		RoHS
73	GL561T0036	LED CY5mm Infrared GL561	SHARP	06.10	797				●	RoHS
74	0026	IC SMD OP SOT23-5 LM7301M5	NS	05.10	0	●				RoHS
76	0005	IC TLP621GR, Toshiba	ST	03.02	774			●		非RoHS
77	0100	IC CMOS 16Pin CD4049UBE	TI	0644	772			●		RoHS
78	0039	IC SMD MCU SO20 STTFL1TE29 F2M6	ST	07.02	755			●		RoHS
79	0004	LIS MITSUBISHI	SHARP	02.07	747	●				RoHS
80	0006	IC SMD MCU 64Pin TQFP UPD78F9456	NEC	0530	704	●				RoHS
81	0033	FET SMD 300mA 60V SOT23 2N7002	PHILIPS	08.01	0	●				RoHS
82	0145	IC SMD OPT-CPR LTV-356T	LITEON	0827	680	●				RoHS
83	0101	IC LM339N "SGS"	ST	05.10	679			●		非RoHS
84	0006	IC SMD 2COMP SO8 UPC393G2	NEC		679		●			非RoHS
85	0051	Shant regurator IC NJM431U	JRC	0609	654	●				RoHS
86	1COB	LSI(CHIP) C38869MFA(MITSUBISHI	LSI	07.02	662	●				RoHS
87	SL245T0061	IC SENSOR 3-Lead TSL245R-LF	TAOS	05.10	580				●	非RoHS
88	02703U0006	IC SMD OPT-CPR 4Pin SOP PS2703-1-F3	NEC	04.12	543			●		RoHS
89	2007	Micro computer IC M38127M8	SHARP		502			●		非RoHS
91	0000	DIODE SK 2*10A 100V TO-220AB	ONSEMI	04	493			●		非RoHS
92	TAKA	M38127MS	Renesas	0408	490			●		非RoHS
93	TAKA	M34225M1	Renesas	05.03	475			●		非RoHS
94	0100	IC CMOS 4040B 16Pin Motorola	Fairchild	0410	471			●		非RoHS
95	00817T0236	PHOTOCOUPLER PC817XP3	SHARP		465		●			RoHS
96	0005	IC SMD DRIVER SSOP24-P-300 TB62706	TOSHIBA	0526	455		●			RoHS
97	0034	IC REG 12V TO-220F KA78R12C	Fairchild	05.10	436			●		非RoHS
98	0113	IC MA1020P, Shindengen			433			●		非RoHS
99	0043	IC REG TO220IS KIA7815API/P	KEC	0604	396			●		非RoHS
100	0007	IC SMD MCU M38254 M8-256FP	Renesas	0718	384				●	RoHS

