

WINDING	START	FINISH	WIRE	WDG. TURNS	TAPE TURNS	
NC	1	NC	2UEW0.250Ø*2	15T	1Ts	密绕一层
N1	3	2	2UEW/Ø0.5	32T	2Ts	密绕二层
N2	1	-	0.05*8mm(Cu Foil)	1.1T	1Ts	
N3	12	10	0.70Ø*2(TEX-E)	4T	1Ts	密绕一层
N3'	12	10	0.70Ø*2(TEX-E)	4T	1Ts	密绕一层
N4	1	-	0.05*8mm(Cu Foil)	1.1T	1Ts	
N5	2	1	2UEW/Ø0.5	16T	2Ts	密绕一层
N6	5	6	2UEW/Ø0.20	7T	1.5Ts	疏绕一层
N7	7	9	0.30Ø(TEX-E)	4T	3Ts	疏绕一层
外铜箔	6	-	0.05*5mm(Cu Foil)	1.1T		铜箔包于铁芯与线包最外包
备注：绕线线头线尾须套铁氟龙套管。						

D.SCHEMATIC(原理图):

