

$NP=P12=0.3X(48.5T+49.5T)=2.13MH$

$NS=P56=0.4X18T(65.3UH)$

$ND=P34=0.3X20T(57.4UH)$

顺序: NP1-NS-ND-NP2
EE22 磁间隙: 100UM*2

